# FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)

- 1. Name of the Office
- 2. Name of the School
- 3. Location with name of Education District/ Sub. District
- Classification of Building as specified in column 4 of the application for fitness certificate and size.

## : ALESTER JOSEPH VANREYK

: Leo XIII English Medium School

: Kalath Ward, Alappuzha

: permanent, RCC roof, three storied building.

### : Ground Floor -

- 1. Stair 2.97 m x 6.28m x 3.62m
- 2. Classroom 8.05m x 6.28 m x 3.62m
- 3. Office room -8.05m x 6.28 m x 3.62m
- 4. Computer lab 9.17m x 6.28 m x 3.62m
- 5. Classroom 8.07m x 6.28 m x 3.62m
- 6. Stair 2.50 m x 6.28 x 3.62m
- 7. Art room -9.25m x 6.28 m x 3.62m
- 8. Classroom 8.08m x 6.28 m x 3.62m
- 9. Chemistry lab 9.29m x 6.28 m x 3.62m
- 10. Classroom 6.28m x 8.18 m x 3.62m
- 11. Classroom 6.28m x 8.25 m x 3.62m
- 12. Stair 2.68 m x 6.28m x 3.62m
- 13. Classroom 6,28m x 8.16 m x 3.62m
- 14. Band 6.28m x 3.84 m x 3.62m
- 15. Verandah 1.67m wide

#### : First Floor -

- 1. Stair 2.97 m x 6.28 x 3.70m
- 2. Classroom 8.14m x 6.28 m x 3.70m
- 3.  $Classroom 8.15m \times 6.28 m \times 3.70m$
- 4. Classroom 9.28m x 6.28 m x 3.70m
- 5. Classroom 8.05m x 6.28 m x 3.70m
- 6. Stair 2.97 m x 6.28m x 3.70m
- 7. Staffroom 9.27m x 6.28 m x 3.70m
- 8. Classroom 8.05m x 6.28 m x 3.70m
- 9. Composite lab 9.30m x 6.28 m x 3.70m
- 10. Classroom 6.28m x 8.23 m x 3.70m
- 11. Classroom 6.28m x 8.23 m x 3.70m
- 12. Stair 2.97 m x 6.28 x 3.70m
- 13. Class room 6.28m x 8.16 m x 3.70m
- .14. Dance & Music 6.28m x 3.84m x 3.70m
- 15. Verandah 1.67m wide

# : Second Floor -

- 1. 1. Stair 2.97 m x 6.28 x 3.70m
- 2. Stage 3.84m x 6.40 m x 3.70m
- 3. Auditorium 23.88m x 6.40 m x 3.70m
- 4. Classroom 6.20m x 6.40 m x 3.70m
- 5. Classroom 8.00m x 6.30 m x 3.70m
- 6. Stair 2.96 m x 6.30 x 3.70m
- 7. Classroom 6.20m x 6.40 m x 3.70m
- 8. Classroom 7.33m x 6.40 m x 3.70m
- 9. Maths lab -7.26m x 6.40 m x 3.70m
- 10. Classroom 6.05m x 6.40 m x 3.70m
- 11. Activity room 6.10m x 8.11m x 3.70m
- 12. Classroom 6.40m x 8.11 m x 3.70m

- 13. Library 6.40m x 8.45m x 3.70m.
- 14. Stair 2.97 m x 6.30 x 3.70m
- 15. Classroom 6.40m x 6.04 m x 3.70m
- 16. Sports room 6.40 m x 6.13 m x 3.70m
- 17. Verandah 1.67m wide

: 01/02/2024 to 31/05/2024

5. Period for which the certificate is issued

6. Nature of defects, if any

- a) Foundation and basement
- b) Superstructure
- c) Doors and Windows
- d) Wood work wrought and put up
- e) Roof
- f) Flooring
- g) Miscellaneous (Cracks, etc.)
- 7. Any major defects noticed which will render the building unsafe in any manner

8. Whether maintenance works have been done properly

9. Whether the structure is sound or not for conducting classes

.

NIL

: NO

YES.

: The structure is sound under normal weather conditions.

Note: 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

## CERTIFICATE

Certified that the school building was inspected by me on 01/02/2024 the period 01/02/2023 to 31/05/2024 for the reasons stated above.

and found to be fit to conduct classes, for

Place:.Alappuzha

Date: .29/05/2023

Coean Coean

Assistant Engineer

ALEST LR JOSEPH VANREYK PEN: 873007

ASSISTANT ENGINEER LID&EW, ALAPPUZHA MUNICIPALITY